


CIRCUIT™ BENCH

SURFACE MOUNT INSTALLATION INSTRUCTIONS

MATERIALS INCLUDED

5/16" hex bit for
tamper-resistant
screws




TOOLS NEEDED




pencil

3/16", 3/8" & 5/8" drill
bits for concrete




hammer drill




steel
wire brush

1/4" punch



hammer

STEP BY STEP FOR ALL SURFACE MOUNTED CIRCUIT BENCHES



1 Mark hole locations


- Place bench in desired location. Mark center of each hole location with a pencil.



2 Drill holes

- Use hammer drill to drill 2-1/4" deep x 5/8" diameter anchor hole at each marked location using a 5/8" drill bit suitable for concrete drilling.

NOTE: Forms+Surfaces recommends starting holes with 3/16" diameter drill bit followed by 3/8" and finally 5/8" for maximum accuracy.




3 Insert & set anchors

- Use compressed air and steel wire brush to clean each anchor hole.
- Insert 1/2"-13 x 2" anchor (a) into each anchor hole and use hammer to tap anchor tops flush with ground level.
- Use 1/4" punch and hammer to set anchors by driving down the center of each anchor until it stops.

CIRCUIT™ BENCH


SURFACE MOUNT INSTALLATION INSTRUCTIONS

STEP BY STEP FOR ALL SURFACE MOUNTED CIRCUIT BENCHES




Position bench

- Position bench so that mounting holes line up with anchors.



Attach bench

- Insert 1/2" - 13 x 1-1/2" tamper-resistant flathead cap screw (b) into each mounting hole in bench and thread into anchors using provided 5/16" hex bit for tamper-resistant screws.



Tighten screws

- Tighten screws until snug.