CROSS TABLE

MATERIALS INCLUDED

a

TOOLS NEEDED

1/2" nut driver

drill

STEP BY STEP   FOR ALL FREESTANDING CROSS TABLES

1

a

Attach table top to column

- Use drill with 1/2" nut driver (or socket wrench with 1/2" socket) to attach table top to column with 5/16"-18 x 3/4" hex head bolts (a).

2

Tighten screws

- Tighten screws until snug.

FORMS+SURFACES®